


Statomų aklų sąrašas,
(viso 12vnt.)

Ds500 Ps16 - 1vnt.
Ds200 Ps16 - 1vnt.
Ds150 Ps16 - 4vnt.
Ds 80 Ps16 - 1vnt.
Ds50 Ps40 - 1vnt.
Ds50 Ps16 - 3vnt.
Ds25 Ps40 - 1vnt.

Aklinimo schema 20KU-1



Schema braižė _____