

Project Title: **SD2026-03 LK-1 RF**

Work package No: **M6-LK-1-RF-PLO**

Job No	OD / Division	Complex / Shop	Section / Dept.	Project DII	Description LT	Description ENG	List of Attachments	JobType	Contractor Type	Contact Person
SD215_1G3104_002	GP-1	LK-1	S-200 BRF		Separatoriaus SP-202 valymas po regeneracijos.	Cleaning of separator SP-202 after regeneration.				
SD215_1G3104_002_006	GP-1	LK-1	S-200 BRF	REM-26002	Talpos, lygio kolonėlių plovimas	Washing of the vessel and liquid chambers	SP-202 plovimo schema.pdf	M	RPLO	Vitkauskas, Vygandas
SD215_1G3104_003	GP-1	LK-1	S-200 BRF		Separatoriaus SP-208 valymas po regeneracijos.	Cleaning of separator SP-208 after regeneration.				
SD215_1G3104_003_007	GP-1	LK-1	S-200 BRF	REM-26002	Talpos, lygio kolonėlių plovimas	Washing of the vessel and liquid chambers	SP-208 separatoriaus plovimo schema.pdf	M	RPLO	Vitkauskas, Vygandas
SD215_1G3104_006	GP-1	LK-1	S-200 BRF		Deaeratoriaus DE-123 inspekcija V.A. (OL).	Internal inspection II (OL) of deaerator DE-123.				
SD215_1G3104_006_024	GP-1	LK-1	S-200 BRF	REM-26002	Talpos, lygio kolonėlių plovimas	Washing of vessel and liquid chambers	LK-1, DE-123 Plovimo schema.pdf	M	RPLO	Vitkauskas, Vygandas
SD215_1G3104_007	GP-1	LK-1	S-200 BRF		Talpos T-202 vidaus apžiūra V.A.(TPT).	Internal inspection of vessel T-202 (LTSS)				
SD215_1G3104_007_007	GP-1	LK-1	S-200 BRF	REM-26002	Talpos, lygio kolonėlių plovimas	Flushing of vessel and liquid chambers	LK-1 T-202 plovimo schema.pdf	M	RPLO	Vitkauskas, Vygandas
SD215_1G3104_018	GP-1	LK-1	S-200 BRF		Šilumokaičio TK-205/4 remontas: produkto praleidimo pašalinimas	Repair of heat exchanger TK-205/4: product leak elimination				
SD215_1G3104_018_006	GP-1	LK-1	S-200 BRF	REM-26002	Vamzdelių pluošto plovimas	Washing of tube bundle	Lk1Tk-205 plovimo schema.pdf	M	RPLO	Vitkauskas, Vygandas
SD215_1G3104_018_007	GP-1	LK-1	S-200 BRF	REM-26002	Korpuso ir gaubtų plovimas	Washing of housing and covers		M	RPLO	Grencius, Edvardas

Job No	OD / Division	Complex / Shop	Section / Dept.	Project DII	Description LT	Description ENG	List of Attachments	JobType	Contractor Type	Contact Person
SD215_1G3107_001	GP-1	LK-1	DK		Kompresoriaus IK-201 (5CD-208/30-45) vidutinis remontas po regeneracijos.	Medium overhaul of centrifugal compressor IK-201(5CD-208/30) after regeneration				
SD215_1G3107_001_004	GP-1	LK-1	DK	REM-26002	Kompresoriaus korpuso plovimas	Compressor housing washing	IK 201 brež.pdf ; IK-201 plovimas.pdf	M	RPLO	Kalvaitis, Vytautas